



## Dual Power supply




### Features: -

- 1x 5V DC output @ 1.5A Max.
- 1x 12V DC output @ 1.5A Max.
- Short circuit protection.
- Fuse protection (comes with 2x 1A QB fuses).
- Thermal overload protection.
- Input voltage range AC 12V to 20V, DC 15V to 30V.

Connections	Function
TB1	AC input (Alternating Current Input)
TB2	5V DC output and 0V
TB3	12V DC output and 0V

This power supply may need extra cooling via a fan at currents over 100mA.

### Approximate PCB dimensions in mm.



### Disclaimer: -

**Caution** cnc machines are very dangerous in the wrong hands; CNC doctor is not liable for any accidents caused by improper use or incorrect connection of our devices. It is up to the operator to maintain his/her Health & Safety. We will not be responsible for damage to the parts of a cnc machine, robot etc. by the incompetents of the user. Devices from CNC doctor are not to be used on anything for life support. The products described here are manufactured under one or more U.K patents or patent pending CNC doctor reserves the right to manufacturer this product. Before placing an order, the user is cautioned to verify that information herein is current and believed to be accurate and reliable.

Please look at our terms & conditions on our website (<http://www.cncdoctor.co.uk>) before you purchase this item.